



Photo 1. Southern end of pond, facing N, overgrown with *Panicum* spp.

Photo 2. Southern end of pond, facing NE



Photo 3. Very dense *Panicum* spp. grass choking out the pond.



Photo 4. Drain pipe is clogging with debris.



Photo 5. North end of pond, facing N, overgrown with *Panicum* spp.



Photo 6. North end of pond, facing NE.

None of the proposed mitigation plants could be seen in any of the proposed locations. The pond is being overrun by a species of *Panicum*.



Photo 7. Banks of discharge pipe are not stabilized.